

	Type	Hits	Search Text	DBs
1	BRS	0	William near4 Palmteer	USPAT; EPO; JPO; DERWENT
2	BRS	0	Palmteer	USPAT; EPO; JPO; DERWENT
3	BRS	3203	William near2 James	USPAT; EPO; JPO; DERWENT
4	BRS	27	(William near2 James) and (solder)	USPAT; EPO; JPO; DERWENT
5	IS&R	608	((("228/180.28") or ("228/180.22"))).CCLS.	USPAT
6	BRS	542	((("228/180.28") or ("228/180.22"))).CCLS.) and (solder\$)	USPAT; EPO; JPO; DERWENT
7	BRS	42969	(core) with (dielectric or ceramic or glass)	USPAT; EPO; JPO; DERWENT
8	BRS	2245	((core) with (dielectric or ceramic or glass)) and (solder\$)	USPAT; EPO; JPO; DERWENT
9	BRS	1634	((core) with (dielectric or ceramic or glass)) and (solder\$)) and (metal\$)	USPAT; EPO; JPO; DERWENT
10	IS&R	1599	((("361/768") or ("361/770") or ("361/771") or ("174/260") or ("174/257"))).CCLS.	USPAT; EPO; JPO; DERWENT
11	BRS	592	((("361/768") or ("361/770") or ("361/771") or ("174/260") or ("174/257"))).CCLS.) and (dielectric or ceramic or glass) and solder	USPAT; EPO; JPO; DERWENT
12	IS&R	236	("257/781").CCLS.	USPAT; EPO; JPO; DERWENT
13	IS&R	1159	((("257/737") or ("257/738"))).CCLS.	USPAT; EPO; JPO; DERWENT
14	BRS	818	((("257/737") or ("257/738"))).CCLS.) and (solder\$)	USPAT; EPO; JPO; DERWENT
15	IS&R	10	((("6265085") or ("6278184") or ("6279815") or ("6101708") or ("6087597") or ("5971253") or ("5838069") or ("5736790") or ("5293001") or ("5093880") or ("6087597"))).PN.	USPAT
16	BRS	194	probiotic	USPAT
17	BRS	176	probiotic and (water)	USPAT; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Errors
1	2001/08/30 17:21			0
2	2001/08/30 17:21			0
3	2001/08/30 17:21			0
4	2001/08/30 17:44			0
5	2001/08/30 17:45			0
6	2001/08/30 17:46			0
7	2001/08/31 09:06			0
8	2001/08/31 09:07			0
9	2001/08/31 09:10		Truncation on Overflow . Return string from Server is: 5'0' 0'ME T	1
10	2001/08/31 10:11			0
11	2001/08/31 10:52			0
12	2001/08/31 10:52			0
13	2001/08/31 11:04			0
14	2001/08/31 14:00			0
15	2001/08/31 14:02			0
16	2001/09/04 10:41			0
17	2001/09/04 10:43			0